

LEGEND

- ◆ Current Compliance Monitoring Wells
- ⊕ Historic Groundwater Monitoring Wells
- ★ Owner Installed Radon Mitigation System

PARCEL OUTLINE

1768 Street Address


MONITORING STATUS

- Testing Performed - No Mitigation System Installed
- Mitigation System Currently Operating
- Mitigation and Monitoring Discontinued with CDPHE Approval

0 90 180 360 540 720 900 Feet

REDFIELD SITE
Denver, Colorado

INDOOR AIR SAMPLING LOCATIONS



Geosyntec
consultants

PLATE 1 OCT 2015
BG-0280 DRH

BASE MAP SOURCE: THIS MAP WAS DERIVED FROM AERIAL PHOTOGRAPHY AND IS NOT INTENDED TO BE A LEGAL SURVEY